

State of Utah

Department of Natural Resources

MICHAEL R. STYLER Executive Director

Division of Oil, Gas & Mining

JOHN R. BAZA Division Director JON M. HUNTSMAN, JR. Governor

GARY R. HERBERT Lieutenant Governor

Representatives Present During the Inspection:					
Company	Dennis Oakley Environmental Engineer				
OGM	Karl Houskeeper Environmental Scientist III				

Inspection Report

Permit Number:	C0150018		
Inspection Type:	PARTIAL		
Inspection Date:	Wednesday, May 21, 2008		
Start Date/Time:	5/21/2008 9:30:00 AM		
End Date/Time:	5/21/2008 2:00:00 PM		
Last Inspection:	Wednesday, April 30, 2008		

Inspector: Karl Houskeeper, Environmental Scientist III

Weather: Overcast/Raining, Temp. 48 Deg. F.

InspectionID Report Number: 1646

Accepted by: jhelfric

Permitee: PACIFICORP

Operator: ENERGY WEST MINING CO

Site: DEER CREEK MINE

Address: PO BOX 310, HUNTINGTON UT 84528

County: EMERY

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Current Acreages

Total Permitted	19,722.21
Total Disturbed	98.05
Phase I	
Phase II	
Phase III	

Mineral Ownership

Types of Operations ✓ Federal ✓ Underground State Surface County ☐ Loadout Processing **✓** Fee Other Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Permit Conditions:

- (1) Underground flows of 5 gpm from roof will be monitored for baseline parameters. Division to be notitified 24 hrs prior to monitoring.
- (2) Submit water quality data for the Deer Creek Mine in an electronic format through the EDI web site.
- (3) No mining on Federal Lease UTU-87285 until approved by Assistant Secretary of Lands & Minerals. Approved by Secretary on October 11, 2006

Inspector's Signature:

Karl Houskeeper, Environmental Scientist III

Date

Wednesday, May 21, 2008

Inspector ID Number: 49

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Permit Number: C0150018 Inspection Type: PARTIAL

Inspection Date: Wednesday, May 21, 2008

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- Substantiate the elements on this inspection by checking the appropriate performance standard.
 For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
- b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
 Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale				
2.	Signs and Markers	V		V	
3.	Topsoil				
4.a	Hydrologic Balance: Diversions	V		✓	
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	✓		V	
4.c					
4.d	Hydrologic Balance: Water Monitoring	✓		✓	
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives				
6.	Disposal of Excess Spoil, Fills, Benches				
7.	Coal Mine Waste, Refuse Piles, Impoundments	V		V	
8.	Noncoal Waste				
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage				
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading				
13.	Revegetation				
14.	Subsidence Control				
15.	Cessation of Operations				
16.a	a Roads: Construction, Maintenance, Surfacing				
16.Ł	Roads: Drainage Controls				
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations				
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other			П	П

Permit Number: C0150018 Inspection Type: PARTIAL

Inspection Date: Wednesday, May 21, 2008

Page 3 of 3

2. Signs and Markers

The ID signs contained the necessary information. The signs are located at the public access to the permit area.

4.a Hydrologic Balance: Diversions

The culvert inlet behind the shop adjacent to the salt storage building has been cleaned.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

The new Rilda sediment pond construction has begun

4.d Hydrologic Balance: Water Monitoring

Fourth quarter water monitoring information is in the EDI website and has been uploaded. Water monitoring is current.

7. Coal Mine Waste, Refuse Piles, Impoundments

The refuse pile appeared stable. No visible hazards.

Material from the new Rilda pond excavation is being hauled to the refuse pile.